



Patea Hydro Electric Power Scheme



Lake Rotorangi Hazard Survey

August 2011

Legal Disclaimer

The report entitled *Lake Rotorangi Hazard Identification Survey* dated 26 August 2011 and the accompanying maps labelled *Lake Rotorangi Hazard Survey (North of HWSC to Glen Nui and South of HWSC to Patea Dam)* ("the information") have been prepared by Discovery Marine Limited, and not by TrustPower Limited.

TrustPower has provided the information to the Hawera Water Ski Club and the Mangamingi Residents for information purposes only and does not make any representation or give any guarantee as to the accuracy or exhaustiveness of the information.

All users of Lake Rotorangi should make their own enquiries and use their own judgment as to the safety and suitability of the Lake for their use. TrustPower will not accept any liability for errors or omissions in the information, or for any injury or damage resulting from reliance on the information.

REPORT OF SURVEY

Report Prepared for:



Lake Rotorangi Hazard Identification Survey

Report Date: 26 August 2011
Surveyed Between: 25 – 27 July 2011



Report Prepared By:



Discovery Marine Ltd
PO Box 4048, Mount Maunganui
Bay of Plenty, New Zealand
Ph: +64 7 579 2955
Fax: +64 7 579 2954
Email: info@dmlsurveys.co.nz

REPORT OF SURVEY

CONTENTS

1. Introduction
2. Equipment
3. Survey Methodology
4. Lake Levels
5. Survey Results
6. APPENDIX A – Hazards
7. APPENDIX B – Lake Bank Photographs

LIST OF ABBREVIATIONS

Abbreviated terms which may be used in this document are as follows:

BM	Bench Mark
CD	Chart Datum
DML	Discovery Marine Ltd
DGPS	Differential GPS
GPS	Global Positioning System
RTK	Real Time Kinematic (GPS Positioning System)
SBES	Single Beam Echo Sounder
SD	Sounding Datum
RL	Reduced Level
TM	Terramodel v10.60
HWSC	Hawera Water Ski Club
GOs	HYDROpro Guidance Objects

Data Acquisition

During survey operations the helmsman was able to use the GOs to navigate along the lake, while the system operator monitored position and depth quality. Where possible a zig zag pattern has been run around the lake edge, from the edge of a safe navigation zone out to 10m depth. Along steep areas no lake bottom was measured as the depth was greater than 10m.

The system operator was able to identify areas that required further investigation, such as shoaling and lake bed features. Position fixes were recorded for hazardous features as well as photographs of features and the lake bank.

Data Editing and Processing

All depth data was processed using the HYDROPro NavEdit software suite. Corrections for transducer offset and lake water levels were applied to the depth database and depth spikes and spurious soundings removed. A manual quality control check of corrected soundings was then carried out.

Edited data was exported into Terramodel v10.60 (TM) software, where depth points were viewed with hazard position fixes to determine a line of safe navigation on the lake. Two 1:10,000 sheets of the lake area were produced to show all hazard areas and the line of safe navigation with the TOPO50 maps overlaid.

In selected areas, ASCII point data was exported to Surfer version 8.0 and gridded at 20m intervals for the production of 2d images.

4. Lake Levels

Lake levels for Lake Rotorangi were provided by TrustPower, for the period the DML survey team were on site. These lake levels were used directly to reduce depth data recorded by DML. The lake level gauge is located at the Patea dam with the level measured at an accuracy of ± 1 cm.

Due to the timing of DML mobilising to the area coinciding with construction work at the HWSC, the lake level was near its lowest consented level of 74mRL during survey operations. The low lake level exposed shallow banks, semi submerged tree stumps and braches and proved beneficial in identifying potentially hazardous areas for recreational lake users.




Figure 1: Graph of Lake Rotorangi Level from 12:00am 25th of July 2011 to 12:00am 29th July 2011. Red box indicates lake level during bathymetric survey operations.

5. Survey Results

DML investigated Lake Rotorangi between Glen Nui and Patea Dam for hazards by surveying an area, where possible between the lake bank and 10m depth. The majority of the lake edge is steep, in some areas the cliff face above the water continues more than 10m below water level and could not be sounded.

The low lake level allowed a visual survey of the lake bank to be undertaken and photographed (Lake bank photos in Appendix B). From analysis of the survey data and photographs, a safe navigation line has been determined around the lake edge and marked on the associated plans (11_13_1 & 11_13_2). The safe navigation line attempts to bound areas where weed or tree stumps and branches are hazardous to recreational lake users.

A number of significant hazards have been identified and numbered on the associated plans. These are outlined further in Appendix A. Shallow areas were noted to extend out from most headlands with the lake bed rising quickly. Caution should therefore be exercised while navigating around headlands close to the lake edge.

Due to the scale of the TOPO50 maps, it is difficult to accurately reference the safe navigation line to the physical lake edge, as the lake edge often deviates from the edge depicted on the NZTOPO50 maps. It is therefore recommended that where lake users are uncertain of the location of the safe navigation line, a minimum of 10m from the water edge be kept to avoid submerged hazards on the lake bed.

D.J. Stubbing
Senior Surveyor
Discovery Marine Ltd

APPENDIX A

A1 - Glen Nui Reach




Figure 2: Colour banded bathymetry in the Glen Nui Reach

Areas of the Glen Nui reach were very shallow with the low lake level. Large sand banks are evident where the lake bends, and at the tributary confluence north of the Caniwi lodge landing. It is recommended that during times of low lake levels this area is navigated slowly or avoided if possible.

A1 – Sand Banks on right bank, opposite Glen Nui Boat Ramp



A1 – Sand Banks on left bank, downstream of Glen Nui Boat Ramp



A1a – Submerged Branches on left bank, downstream of Glen Nui



A line of partially submerged branches extending approximately 10m perpendicular to the lake edge.

A1b – Tree Stumps/Roots on left bank, downstream of Glen Nui



A line of tree stumps that would be submerged with regular lake levels. This is near a lake corner where recreational boat users apparently come close to the lake edge.

A2 – Fallen Pine Tree on left bank.



A large dead pine tree has collapsed into the lake. There are several partially submerged branches and hazards in the immediate area surrounding the tree..

A3 – Semi Submerged Braches on left bank



A large area of lake bank with several bare tree trunks extending into the lake.

A3 – Semi Submerged Braches on left bank



A4 – Exposed Tree Branch on left bank downstream of Otairira Stream




An exposed tree branch extends 10m out from the lake bank, 1m above the lake level. Will cover with normal lake levels

A4 – Exposed Tree Branch on left bank



Photo of tree hazard extending into lake.

A5 – Large Semi Submerged Tree Area on right bank downstream of Otairira Stream.



A large shallow hazard area extends off this headland and is covered with weed, tree stumps and branches. With the low lake level it was evident that the scattered submerged tree branches extend out into the lake as shown above by the hatched hazard area.

A5 – Large Semi Submerged Tree Area on right bank downstream of Otairira Stream.



Photo of the lake bank with tree stumps, branches and weed.

A5 – Large Semi Submerged Tree Area on right bank



Photo of the lake bank with tree stumps, branches and weed.

A5 – Large Semi Submerged Tree Area on right bank



Photo of the lake bank with semi submerged branches in the foreground.

A6 –Submerged Tree Stump on left bank, upstream of HWSC



A 0.3m diameter tree stump was found submerged 0.05m and 5m from the lake edge. It is outside the safe navigation zone and close passage around this headland should be avoided.

A6 –Submerged Tree Stump on left bank, upstream of HWSC



Photo showing approximate location of submerged tree stump.

A7 – Weed covered shallow sandy area on left bank, upstream of HWSC



A sandy, weed covered bank extends into the confluence from the southern headland. There are large floating areas of weed in this area also

A8 – Submerged tree stumps close to bank on left bank opposite HWSC



Several tree stumps submerged 0.05m have been seen close to the bank in this area opposite HWSC.

A9 – Weed covered, shallow, sandy area on left bank opposite Pukekino Road



A large sandy, weed covered bank extends out from the entrance to two small lake arms and a landing area. Bank was approximately 0.5m above the low lake level. There were also large areas of floating weed surrounding the bank

A9 – Weed covered, shallow, sandy area on left bank opposite Pukekino Road



Photo of a tree hazard close to the lake bank in the north of this area. Tree would be submerged with normal lake levels.

A10 – Felled trees on bank extending to water line & submerged on left bank, downstream of Pukekino Road



Fallen tree extending from lake bank into water. The end of this tree is submerged approximately 5m from lake edge. Tree would be covered with normal lake levels.

A11 – Submerged branches and weed near bank on right bank downstream of Pukekino Road



Tree branches extending out from shallow headland into water. Avoid passage close to the headland when entering small bay.

A12 – Submerged branches & weed near marker buoys on right bank



Several isolated tree branches and areas of floating weed have been seen, 5 to 10m off the lake bank close to some marker buoys. These buoys may be used as part of a ski lane. It is recommended that close passage to the lake bank be avoided in this area or the buoys moved further from the bank.

A13 – Small Raft/Wreck on right bank




What appears to be an upside down raft was found loosely tethered to the land. It is unsure whether this raft is floating or submerged when the lake is at its normal level.

A14 – Fallen trees on bank and semi submerged branches on right bank



Photo showing tree stumps and branches extending into the lake on a narrow headland. Close passage to this headland should be avoided.

A15 – Normally submerged land area on right bank



Three clumps of bush that appear partially submerged at normal lake levels. It is recommended lake users avoid passage between these as its is shallow an there are numerous semi submerged branches surrounding them.

A16 – Partially Submerged Barge/Caravan on left bank, upstream of Patea Dam



A partially submerged caravan barge was discovered tethered to the lake bank. It is recommended lake users avoid this area as the barge may break free and become fully submerged.

A17 – Patea Dam



A large boom extends across the lake in front of the dam wall.

APPENDIX B

B1 – Left Bank



B2 – Right Bank



B3 – Right Bank



B4 – Right Bank



B5 – Left Bank



B6 – Left Bank



B7 – Left Bank



B8 – Left Bank



B9 – Right Bank



B10 – Right Bank



B11 – Left Bank



B12 – Right Bank



B13 – Right Bank



B14 – Right Bank



B15 – Right Bank



B16 – Right Bank



B17 – Left Bank



B18 – Right Bank



B19 – Left Bank



B20 – Right Bank



B21 – Left Bank



B22 – Left Bank



B23 – Right Bank



B24 – Left Bank





B25 – Left Bank





B26 – Left Bank






 Surveyed By Discovery Marine Ltd Hydrographic and Coastal Management Services POBox 4048, Mt Maunganui, Bay of Plenty, New Zealand info@dmlsurveys.co.nz www.dmlsurveys.co.nz	Datum:	NZGD2000	Project:	Lake Rotorangi Hazard Survey	Survey Date:	25,26, 27 July 2011
	Grid:	NZTM	Drawing:	North of HWSC to Glen Nui	Scale:	1:10,000
	Vertical:	Patea Dam			DML Job ID:	11_13
					DWG No.:	11_13_1





 <p>Surveyed By Discovery Marine Ltd Hydrographic and Coastal Management Services POBox 4048, Mt Maunganui, Bay of Plenty, New Zealand info@dmlsurveys.co.nz www.dmlsurveys.co.nz</p>	Datum:	NZGD2000	Project:	Lake Rotorangi Hazard Survey	Survey Date:	25,26, 27 July 2011
	Grid:	NZTM	Drawing:	South of HWSC to Patea Dam	Scale:	1:10,000
	Vertical:	Patea Dam			DML Job ID:	11_13
					DWG No.:	11_13_2

